MAD ZOI

MAP CO
808/501
(423 -21)
1 822 814 345 WASH 1997
 MT VERUOD 366
367
KENT
818
810
367- John Seidel MLM (40/203
36 Woodrow Loller EHP 157/4
365 Frederick Land MLM 111/443
 818 Raymond Walls (238) MLM7/257
/819 Samuel Massay 231/ WH6 26/309
821 Betty Hard 520(234) MLM56/48
822 Sylvia Maloney 232) £4P265/409
 Massey - WHG 26 (309
Lots 61 876 Wash Cod. lands 584/224
Begin ph. Ok whide it at co. Coleman
W/s N der 140° to bulliains
us 1 ts 50' + to May Inde
ufs sidur 10' =
W/s H- & E du 10' to Douchkin
W/s 5 du 70' to Kent St
less w dir. 60+ to begin
Hard- MLM 56/48
 50
 139

162 /308 31/5 114/300 367 - 2061 Seedel MIM (40/203 Wounder Louier EHP 157/4 Frederick Land My MI 115 200 Eagmon State (232) WLMT/237 July 1025 - 123 1116 76 201 ELTH FIRST 50(234) MINISOLAS 202 Eyra Malaray Est Expers Mag 11: 14 - Was El (201 54,224 The bearing the lange Collins ACC 450 An Swarty 113 Co 11 1 140 t by by by hillian 1 1 10 50 = 1 Though duch with the 19 and My or the Edit 15 & to there were is you sor is . me at legin 5+100111111111

50 5593-4-749

Malls - MLM7/257 Begin N side Kent. a/ Clark N der. 69'6"+ rt KS w Sides E du. 60° to Usellon les 5 dec. 69'6" + to Kent Us W der 60° to begin Loller - RHP 157/4 69 6" on brash Ove x 200' deep. SEE to Marry - WH6 45/132 $\ell \ell^{\pm}$ 40°± -/'± 70°± Land MLM 11/448 w/ Massy, & Hard 589°00'w - 280 to 6. 1000 pin

NO2º 00 W- 69.58 to HA

Bill Carroll-1992

Mr. Woodrow W. Loller 204 Washington Ave. Chestertown, Md. 21620

Dear Mr. Loller:


I have looked over the correspondence and plats that you furnished me concerning the property line between your lot and that of the Clarks.

In my survey of the then Barnhart lot in 1999 I was aware of the plat by George Elder in 1956. I debated whether the east line of Barnhart should jog 1' east of the corner of Walls or whether the logical line was a straight line from Kent Street to the lands of Frederick Land. I decided on the later course for the following reasons. The plat by Elder leaves a lot to be desired: all distances are "more or less", no bearings were shown and the 90 angles are incorrect, they should be 89 or 91. Furthermore, Mr. Elder was not a surveyor but a C.E. (Civil Engineer), and I seriously doubt that any measurements were made or the original property corners located and verified. This was a judgement call on my part.

Mr. Clower's contention that the Scott survey and mine do not agree is not true. The Scott plat was an improvements location or mortgage survey done to locate improvements and to assure the bank that everything was on the lot. He did not put bearings on the lines, but all of the distances were the same. The two "iron pipes found" shown on his plat are the ones that I set in the Barnhart survey..

The Clarks could possibly have claim to a 1' strip beyond the line that I established, but I will stand behind my survey.

Sincerely yours,



KENT STREET



PLAT OF A SURVEY OF THE RENEE M. BARNHART LANDS


CHESTERTOWN, KENT COUNTY, MO.

Scale | "=20"

May 1999.

William R. Nutle, Reg. Surveyor Chestertown, Md.

1.P. = iron pipe



KENT STREET



PLAT OF A SURVEY OF THE WM. F. KALINE, JR. LANDS
CHESTERTOWN, KENT COUNTY, Mo.
Scale ("=20" May 1999.

William R. Nuttle, Reg. Surveyor Chestertown, Md.

I.P. = iron pipe